




J BOTTOM TRACKS

N COMPONENT IDENT - BOTTOM

ASSEMBLY NOTES

1. ENSURE CORRECT ORIENTATION OF COMPONENTS
2. MOUNT GROUND BARS AS HIGH OFF OF THE BOA
3. ACCEPTABLE BOARD BOW/TWIS
4. RELEASE
5. SOLDER RESIST
6. COPPER FILL MAY BE ADDED
7. CONSULT ENGINEER IF THIS
8. SOLDER RESIST
9. COMPONENT IDENT.
10. RELEASE

PC3462M	
LAYI	
LAYER	DESCRIPTION
M	COMPONENT IDENT. - TOP
K	SOLDER RESIST -TOP
A	TOP TRACKS
B	GND/POWER1 PLANE
C	INNER TRACKS 1
D	POWER PLANE
E	INNER TRACKS 2
F	INNER TRACKS 3
G	GND PLANE
H	INNER TRACKS 4
I	GND/POWER2 PLANE
J	BOTTOM TRACKS
L	SOLDER RESIST - BOTTOM
N	COMPONENT IDENT. - BOTTO