J. ACCEPIADLE DUARD DOW/IWIE

ASSEMBLY NOTES

6. COPPER FILL MAY BE ADDED SOLDER PASTE MASTERS, ANATICARIE ASSEMBLY TOP SOLDER PASTE - PC3462M/1 O FACE BOTTOM SOLDER PASTE - PC3462M/1 P FACE BOTTOM ASSEMBLY DRG. AVAILABLE - A2-TE-0156

- 1. ENSURE CORRECT ORIENTATION OF COMPONENTS 8. SOLDER RESIST VISIBLE WHERE POSSIBLE.
- 2. MOUNT GROUND BARS AS HIGH OFF OF THE BOA COMPONENT IDENT.

10. RELEASE

PC3462M	
	LAYI
LAYER	DESCRIPTION
M	COMPONENT IDENT TOP
K	SOLDER RESIST -TOP
A	TOP TRACKS
В	GND/POWER1 PLANE
С	INNER TRACKS 1
D	POWER PLANE
E	INNER TRACKS 2
F	INNER TRACKS 3
G	GND PLANE
Н	INNER TRACKS 4
I	GND/POWER2 PLANE
J	BOTTOM TRACKS
L	SOLDER RESIST - BOTTOM
N	COMPONENT IDENT BOTTO

H INNER TRACKS 4